


3DSIMO - BASIC 2

INSTRUCTION MANUAL


set contains




3DSIMO BASIC 2



service key






USB charging cable




PCL material

Charge your device before first use

controls & elements




service cover acces




You can easily maintain your 3DSIMO Basic 2
 1. Open service cover with service key.
 2. Remove all grinded material and dust, then put cover back onto Basic 2.

insertion of material




hold extrusion button and check if your material is feeded into the nozzle.
 After a while, you will see material going out of the nozzle.

ejection of material



device charging



charging cycle

charging done